

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## **IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

09429641.102999




Fig. 1

INDICUM (SPICE) No.	IMAGE DATA	ESTIMATED LOSS (DB)	CLEAVE ANGLE(DEG)	SPLICE PROGRAM	DATE/TIME OF MANUFACTURE	OPERATOR	SPICER NO.	INITIALLED LOCATION	CROSS- REFERENCE
31804		0.07	0.14 0.25	1	2/25/99 11:31 AM	JONES	2	105-A1-B22	31805, 31806
31805 221		0.09	0.21 0.32	1	2/25/99 11:53 AM	JONES	2	103-A1-B23	31804, 31806
23A17		0.06	0.48 0.12	4	1/15/99 2:47 PM	SMITH	1	115-A7-103	23A15, 23A16, 23A18
72W42		0.09	0.17 0.63	2	12/14/98 1:14 PM	DOE	3	112-A3-72	72W40, 72W41, 72W43, 72W44

Fig. 2

09429641-102999

66201-1432460




Fig. 3

66620T 14962460




Fig. 4

666201-14962460




Fig. 5

042941092460




Fig. 6

666207-14962460




Fig. 7



666201" T4962460




Fig. 8

09423644 102999




Fig. 9

666201-14962460




Fig. 10